Cable UNIT 2293290-501,507 DMG NO. SHUTTLE CCTV W 7.8 FMEA NO. 1SSUE0 10-14-86 CRITICAL ITEMS LIST SHEET CRITICALITY 2/1R FARLURE MODE AND FAILURE EFFECT RATIONALE FOR ACCEPTANCE ON END ITEM CAUSE DESIGN FEATURES 1) No video from wrist Lass of +28V power (RMS) camera stack The K7 RYS/AMS cable is a 20-inch long assembly, 35-wire assembly. The cable is 2) Na video from elbow Open/Short to GMD terminated on each end with a 37-pin connector (P), KJ66E14M35SW16). The video and sync camera stack wires are shielded #24 Twinax twisted-pair wires. The W7 cable provides power and 3) No elbow PTU control commands from the RVS to the RMS wrist or elbow camera stack and returns video signals to the RVS. Worst Case: The cable design is taken from the successfully flown Apollo program. The design is a No PTU control of elbow cable-connector assembly in which the wire terminations are protected from excessive camera which prevents flexture at the joint between the wire and the connector terminal. The load arm stowage. concentration is moved away from the conductor connection and distributed axially along the length of the conductors encapsulated in a potted-taper profile. This technique also protects the assembly from dirt and entrapped moisture which could cause problems in space. The cable and its components meet the applicable requirements of NASA, Hilitary and RCA specifications. These requirements include: General/Mechanical/Electrical Features Design and Construction Materials Terminal Solderability Environmental Qualification Marking and Serialization Traceability and Documentation

REVISED 5-7-87

FMEA NO. W 7.8 CRITICALITY 2/3R		SHUTTLE CCTV CRITICAL ITEMS LIST	ONG NO. 2293290-501,502 15SUED 10-14-86 SHEET 2 UF 5
FATLURE MODE AND	FAILURE EFFECT ON END LITEN	RATIONALE FOR ACCEPTANCE	
oss of +28V power (RMS) pen/Short to GMD	i) No video from wrist camera stack 2) No video from elbow camera stack 3) No elbow PTU control Worst Case: No PTU control of elbow camera which prevents arm stowage.	Qualified by 1.) similarity to previous successful qualification tests of CCTV LRUs. ACCEPTANCE TEST The cable acceptance test consists of am observer connection is present and intact. Results are reconnection is present and intact. Results are reconnected in the following tests verify that CCTV components are the PMS (A7AI) panel switch, through the RCU, there to the Camera/PTU command decoder are proper. The ability to produce video, the VSU's ability to reconsist verifies the MOM confidence of the CCTV System. Pre-Launch on Orbiter Test/In-Flight Test 1. Power CCTV System. 2. Select a monitor vis the PMS panel, as destination. 3. Send "Camera Power On" command from PMS panel select "External Sync" on monitor. If video stable raster), then this indicates that the from the RCU and that the camera is producting stable raster), then this indicates that the from the RCU and that the camera is producting the RCU and that the camera is producting of irrect observation) verify proper. Select Downlink as destination and camera und Boserve video routed to downlink. Send "Camera Power Off" command via PMS panel to Repeat Steps 3 through 9 except issue comman proves that the CCTV equipment is operational.	check to assure that each wire corded on data sheets. The operable and that the commands from the sync lines to the Camera/PTU stests also verify the camera's rise video and the monitor's ability to a synchronized the camera under test as to on monitor is synchronized (i.e., camera is receiving composite sync g synchronized video. Onmands and visually (either via the operation. der test as source. 1. ds via the MDM command path. This

FMEA NO. W 7.8 CRITICALITY 2/1R		SHUTTLE CCTY CRITICAL ITEMS LIST	UNIT Cable OMG NO. 2293290-501,502 1\$SUEO 10-14-86 SMEET 3 UF 5	
FAYLURE HODE AND FAYLURE EFFECT CAUSE ON END ITEM		RATIONALE FOR ACCEPTANCE		
oss of +28V power (RMS) pen/Short to GND	1) No video from wrist camera stack 2) No video from elbow camera stack 3) No elbow PTU control Worst Case: No PTU control of elbow camera which prevents arm stowage.	Procurement Control - Mire, connectors, solder, etc. are procured from approved vendors and suppliers which meet the requirements set forth in the CCTV contract and Quality Plan Work Statement (NS-2593176). Incoming Inspection & Storage - Incoming Quality inspections are made on all received materials and parts. Results are recorded by lot and retained in file by drawing and control numbers for future reference and traceability. Accepted items are delivered to Material Controlled Stores and ratained under specified conditions until cable fabrication is required. Non-conforming materials are held for Material Review Board (MRB) disposition. (PAI-307, PAI 1QC-53). Assembly & Test - Prior to the start of assembly, all items are verified to be correct by stack room personnel as the items are accumulated to form a kit. The items are		
		verified again by the operator who assembles the kit to as-built-parts-list (ABPL). Specific instructions are given in assembly drawing not called out in the Fabrication Procedure and Record (Process Standard crimping flight connector contacts, splicing of standard interconnecting wire using Raych Process Standard marking of parts or assemblies with material and test procedure (TP-AT-2293290). Quality at the completion of key operations.	otes and applicable documents PR-2293290). These are 2280800 - 2280801 - Process Standard in-line em solder sleeves, 2280876 - epoxy colors, 2280876. Potting and OCAS Inspections are performen	
		Preparation for Shipment - When fabrication and test packaged according to 2280746, Process Standard for P. All related documentation including assembly drawings is gathered and held in a documentation folder assign assembly. This folder is retained for reference.	ackaging and Handling Euldelines. . Parts List. ABPL, Test Data, etc.	

REVISED 5-7-87

FNEA NO. W 7.8 CRITICALITY 2/1R	· · · · · · · · · · · · · · · · · · ·	SHUTTLE CCTV CRITICAL ITEMS LIST	18411 Cable DMG NO. 2293290-501,502 155UED 10-14-86 SMEET 4 OF 5
FATLURE MODE AND CAUSE	FAILURE EFFECT ON END TIEM	RATIONALE FOR ACCEPTANCE	
oss of +28V power (RNS) Ipen/Short to GNO	i) No video from wrist camera stack 2) No video from elbow camera stack 3) No elbow PTU control Worst Case: No PTU control of elbow camera which prevents arm stowage.	FAILURE MISTORY There have been no reported failures during RCA t	testing, pre-flight or flight.
•			

REVISED 5-7-87

FMEA NO. M 7.8 CRITICALITY 2/3R		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT C45 18 DMG NO. 2293290-501,502 ISSUED T0-14-86 SHEET 5 OF 5
FAYEURE MODE AND CAUSE	FATURE EFFECT ON END ITEM	OPERATIONAL EFFECTS Loss of ability to position the Elbow camera. Possible inability to stow the RHS if the elbow camera physically interferes with a payload. If RMS cannot be stowed the port payload hay door cannot be closed. Loss of crew and wahicle. CREM ACTIONS Perform EVA to reposition the elbow camera, use RMS motion to reposition the camera, or juttison the RMS. CREW TRAINING Crew should be trained in contingency EVA and RMS operations procedures. MISSION CONSTRAINT Do not manifest Elbow camera for any flight where the payload and the elbow camera can interfere with each other (for any pan or tilt angle). If the camera must be flown do not change the camera position until the interfering payload is deployed.	
Lass of +28Y power (RMS) Open/Short to GMO	1) No video from wrist camera stack 2) No video from elhow camera stack 3) No elbow PTU control Worst Case: No PTU control of elbow camera which prevents arm stowage.		